



中國香港賽艇協會
HONG KONG, CHINA ROWING ASSOCIATION

重要通告

沙田賽艇中心更衣室走廊位置電燈系統故障

由於沙田賽艇中心近更衣室走廊位置受到電力故障因素所影響，因此該位置的電燈系統未能如常運作，直至另行通知。本會已安裝臨時照明系統，還請各中心使用者在走廊位置活動時加以小心。不便之處，敬請原諒。

Important Notice

Lighting system next to the changing room failure at the Sha Tin Rowing Centre

Due to the electricity interruption, the lighting system next to the changing rooms is affected. The immediate replacement action was taken by the HKCRA already and emergency lighting system was installed. We would like to remind all centre users to pay attention and be careful when they are moving in the mentioned area.

We apologize for any inconvenience caused and thank you for your understanding.

中國香港賽艇協會
Hong Kong, China Rowing Association
31/7/2017